

Lathe, Automatic

Reference Number: 1264

Machine:

Model: #2

Serial: 542-2-5728-15/8

Year of MFG: 1964

Description:

Automatic Screw Machine #2

Operational 4 speeds, 1 5/8 CAP Spindle, Quick change gear for 240 RPM Spindle, Coolant system, 10' Bar feed control with timer, Work Lamp

Electrics:

Volts 220, Amps 26, Phase 3



Reference Number: 1255

Machine:

Model: #2

Serial: 542-2-316-3/4

Year of MFG: 1952

Description:

Automatic Screw Machine #2

3/4" Capacity Spindle, Variable Speed, Quick Change Gear for a 240RPM Drive Shaft, Self Contained Cooland System, 10' Bar Feed, Control withTimer

Electrics:

RPM - 240, PH - 3

